



Notice of possible L5AWM Compatibility Issue

May 29, 2015

To Our Valued Distributors:

Lancer has been made aware of a potential compatibility issue with L5AWM magazines with a date code of March 2015 (3/15). These L5AWMs may contain a non-conforming follower. The non-conforming followers, which were manufactured below the allowable limit of tolerance, could fail to lock the bolt back after the last round is fired in a small percentage of rifle platforms.

I sincerely apologize that you and your customers may have received anything less than a 100% reliable Lancer product. You do not need to take any corrective actions at this time. We have issued a public statement to make end users aware of the issue, instructing them to contact us directly with questions and for a replacement follower free of charge. Please forward all warranty or customer service issues to Lancer at LSWarranty@Lancer-Systems.com. The statement and replacement procedure can be found on our [website](#). For additional questions, please call 610.973.2644.

The reliability of our L5AWMs, and every product we engineer and manufacture, is our absolute highest priority. We've corrected this manufacturing issue and have taken specific steps to ensure our followers always meet the highest standards so our customers can continue to fully trust their Lancer magazines.

We appreciate your business and your continued support. If you have any questions, please contact us. You can call your sales rep, or me directly at the number below.

Sincerely,

Bill Meiklejohn
President, Lancer Systems
610.973.2616