



IMPORTANT SAFETY NOTICE

for
Retailers and Distributors

July 2008

Dear Valued Customer:

Our records indicate that you have purchased the Crosman Firestorm Slingshot (Model FSS) and/or the Crosman Tapered Replacement Bands (Model TRB). We have recently discovered a potential problem with the plastic clips attached at the ends of the bands sold on the Firestorm Slingshot and also sold separately as tapered replacement bands.

We believe some of the plastic clips on the bands may have the potential to break when the band is drawn back. If the band is drawn back toward the eye or other part of the face or body, there could be a risk of serious personal injury, especially to the eye.

These bands were sold from February 2003 through June 2008. Only these bands with the attached plastic clips are the subject to this safety notice.

Please stop selling Model TRB replacement bands or any Model FSS slingshots that have bands with plastic clips attached at the ends. We ask that you destroy these products and provide Crosman certification of the destruction. (A form is attached for your convenience.) Please contact your Sales Representative for details about replacements.

If you have sold any of these models as a distributor, you must notify your distribution customers of this important safety information. Please provide them with a copy of this information.

We will provide you with copies of the "Important Safety Notice" to Consumers and Consumer Request Form for Replacement Form to be available to consumers in your store. This information will also be posted on our website www.Crosman.com Please contact your Crosman Sales Representative if you have questions.

We appreciate your assistance and apologize for any inconvenience this may cause you. Thank you for your patience and cooperation.

Sincerely,

A handwritten signature in black ink, appearing to read "Bob Hampton", is written over a horizontal line.

Bob Hampton
Vice President, Marketing

Innovation and Quality since 1923

Crosman
Tapered Replacement Band
Firestorm Slingshot
 July 2008

Model	Description	UPC #
FSS	Firestorm Slingshot	028478124547
TRB	Tapered Replacement Band	028478124578

CHECK LIST

1. Stop selling the above-referenced products, which were sold with plastic clips attached at the ends of the band.
2. Arrange to destroy these products, complete Destruction Certification below, and fax it to your Sales Representative. Make additional copies of the Certification if necessary. Ultimately Crosman will need a list from each company as to the total number of each Model (FSS and TRB) that was destroyed.
3. If you have sold these models as a distributor, you will need to notify your customers by sending them a copy of the "Important Safety Notice for Retailers and Distributors" and this Form. Your customers should complete this Form, and also provide full shipping address and contact name for replacements.
4. Be prepared to provide copies of the "Important Safety Notice" to Consumers and Consumer Request Form for Replacement Form to consumers in your store.
5. Talk to your Sales Representative for details about replacements.

Destruction Certification

Model FSS or TRB	Number destroyed	Print name and title	Print company name (Also Store # or location if applicable)	Signature	Date

By signing this document I state that I have destroyed or overseen the destruction of the products listed and can confirm that these products were actually destroyed.



IMPORTANT SAFETY NOTICE

July 2008

To Consumers who have purchased the Crosman Firestorm Slingshot (Model FSS) and/or the Tapered Replacement Bands (Model TRB)

This Notice contains important information regarding the Crosman Firestorm Slingshot (Model FSS) and the Crosman Tapered Replacement Band (Model TRB). We have recently discovered a potential problem with the plastic clips attached at the ends of the bands sold on the Firestorm Slingshot and also sold separately as tapered replacement bands.

We believe some of the plastic clips on the bands may have the potential to break when the band is drawn back. If the band is drawn back toward the eye or other part of the face or body, there could be a risk of serious personal injury, especially to the eye.

These bands were sold from February 2003 through June 2008. Only these bands with the attached plastic clips are the subject of this safety notice.

Please stop using any bands with plastic clips attached at the ends. Discard those bands, and contact Crosman to get a free replacement band.

If a Request Form for a free replacement band is not enclosed or attached, a Request Form can be completed online and/or is available for download at [Crosman.com](http://www.crosman.com) website, see http://www.crosman.com/site/safety_notices. You can reach Crosman Customer Service at 1-800-724-7486.

Visit our website (Crosman.com-Safety and Education) for updates on this information. We appreciate your assistance and apologize for any inconvenience this may cause you. Thank you for your patience and cooperation.

Sincerely,

A handwritten signature in black ink, appearing to read "Bob Hampton", is written over the printed name.

Bob Hampton
Vice President, Marketing

Innovation and Quality since 1923

