



## SIG SAUER ROMEO5 RECALL

Dear Retailers and Distributors,



SIG SAUER, in cooperation with the U.S. Consumer Product Safety Commission, is recalling the ROMEO5 Red Dot Sight manufactured in 2023 or 2024. The recalled firearm sights pose an ingestion hazard because the product contains a CR2032 button cell battery can be easily accessed and do not bear the required warnings. In addition, there is a button cell battery provided in the retail package which is not in child-resistant packaging. These are violations to the mandatory federal regulations for consumer products containing button cell batteries required by Reese's Law. When button cell batteries are swallowed, the ingested batteries can cause serious injuries, internal chemical burns and death, posing an ingestion hazard to children.

This recall involves Models SOR52001 and 7400579, which is a part included with Model SORJ53101. The recalled ROMEO5 sights have a knurled battery cap and contain either the letter K or M as the last digit of the serial number printed on the bottom of the sight. Consumers are being instructed to immediately stop using the recalled firearm sights and contact SIG SAUER and to contact us for instructions on how to receive a free recall kit.

If you have any direct contact information for consumers who purchased the recalled product, please send them the attached consumer letter. For retailers, please display the attached in store poster in a conspicuous location for 120 days, May 8, 2025.

If you have affected units of ROMEO5 in stock, the products cannot be offered, sold, or distributed. Continued distribution and sale of the products constitutes a violation of federal law. Products in inventory must be quarantined for reconditioning to render them compliant with Reese's Law. SIG SAUER will contact you with instructions on how reconditioning will be conducted and/or will provide product return/replacement options that are compliant with Reese's Law. If you have any questions about this notice or how to identify the affected products, please reach out to SIG SAUER at [ROMEO5StopSale@sigsauger.com](mailto:ROMEO5StopSale@sigsauger.com) or call SIG SAUER Dealer Services at 603-610-3000 (Option 2).

For reference, if the ROMEO5 units that you have in inventory have the new compliant battery cap, then those units will also have the compliant warning label on the box as shown below, and these units are NOT affected by the Recall or the Stop Sale.

 <b>WARNING</b>	
<ul style="list-style-type: none"><li>• <b>INGESTION HAZARD:</b> This product contains a button cell or coin battery.</li><li>• <b>DEATH</b> or serious injury can occur if ingested.</li><li>• A swallowed button cell or coin battery can cause <b>Internal Chemical Burns</b> in as little as <b>2 hours</b>.</li><li>• <b>KEEP</b> new and used batteries <b>OUT OF REACH OF CHILDREN</b>.</li><li>• <b>Seek immediate medical attention</b> if a battery is suspected to be swallowed or inserted inside any part of the body.</li><li>• Battery type: CR2032</li><li>• Nominal voltage: 3V</li></ul>	
7405414 R00	

Thank you for your cooperation in this matter.



## **SIG SAUER ROMEO5 RECALL**

Dear Customer,

SIG SAUER, in cooperation with the U.S. Consumer Product Safety Commission, is recalling the ROMEO5 Red Dot Sight manufactured in 2023 or 2024. The recalled firearm sights pose an ingestion hazard because the product contains a CR2032 button cell battery can be easily accessed and do not bear the required warnings. In addition, there is a button cell battery provided in the retail package which is not in child-resistant packaging. These are violations to the mandatory federal regulations for consumer products containing button cell batteries required by Reese's Law. When button cell batteries are swallowed, the ingested batteries can cause serious injuries, internal chemical burns and death, posing an ingestion hazard to children.

Consumers should immediately stop using the recalled firearm sights and contact SIG SAUER for instructions on how to submit a picture of the serial number to receive a free recall kit which includes a new cap with the required labeling and an updated instruction manual.



This recall involves Models SOR52001 and 7400579, which is a part included with Model SORJ53101. They are black in color and labeled with the SIG SAUER logo and ROMEO5 name on one side of the product. The model number can be found on the product packaging. The recalled ROMEO5 sights have a knurled battery cap and contain either the letter K or M as the last digit of the serial number printed on the bottom of the sight. Please see instructions below to determine if your ROMEO5 sight is affected by this recall.

Thank you for your cooperation in this manner.

## STEP 1

Remove the optic from your firearm and use a T10 Torx driver to remove the mount from the optic main assembly.



## STEP 2

Locate your serial number and confirm whether or not it ends with an "M" or a "K".

**Note:** When reinstalling your mount to the main assembly, the four mounting screws should be torqued to a spec of 10 in/lbs."



## UPDATED BATTERY CAP FOR SIG SAUER ELECTRO-OPTICS



NON-COMPLIANT KNURLED BATTERY CAP



UPDATED COMPLIANT BATTERY CAP

**SIG SAUER**

EFFECTIVE 12.2024

For more information on this recall and to receive a free ROMEO5 Recall Kit with a new compliant battery cap, please contact Sig Sauer at 603-610-3000 from 8:30 a.m. to 5 p.m. ET Monday through Friday, email at [ROMEO5Recall@sigsauer.com](mailto:ROMEO5Recall@sigsauer.com) or online at <https://www.sigsauer.com/safety-center/> or <https://www.sigsauer.com> and click "Recall Notices" at the bottom of the page for more information.