

IMPORTANT SAFETY RECALL

Weatherby Stainless Steel Vanguard Rifles

Weatherby has found on some Stainless Steel Vanguard Rifles the barrel nut is not tightened to the required torque specifications. The use of the rifle with an improperly torqued barrel nut, may lead to a failure in a discharge situation which could result in a personal injury.



! WARNING: If the serial number of your Weatherby Stainless Steel Vanguard rifles is included in the Serial Number list, your rifle is part of the recall.

PLEASE STOP USING YOUR AFFECTED RIFLE IMMEDIATELY until it has been inspected and if necessary, repaired by the Weatherby Repair Center.

Use of an affected rifles may result in an accident and/or severe injury.

To determine if your rifle is affected by this recall and to **Register your Rifle** for the free inspection and/or repair, please go to the Weatherby Registration Center at the link below.

The affected Serial Number ranges are:

VS383193 - VS383892	VB007201 - VB007400
VS386493 - VS387192	VB010401 - VB010700
VS389928 - VS390492	VB013401 - VB013700
VS393573 - VS393792	VB015901 - VB016400
	VB018901 - VB019400
	VB022501 - VB022600

For additional information, please contact the Weatherby Registration Center:

(888) 770-7138

or enter this link online

<http://www.regcen.com/vanguard/Register.aspx>