



MAXIM DEFENSE 300 BLACKOUT SERVICE RETURN REQUEST

Maxim Defense is committed to the highest quality, reliability, and safety of our products. We continually test evaluate as well as respond to feedback from our end users.

With this level of commitment, we have identified a potential safety concern with our 300 Blackout line of PDX firearms and Upper Receiver Group Assemblies. (See Product SKUs Below) We have determined that in certain circumstances, there is a possibility that excessive gas pressures could leak from around the gas block under the handguard

While this may have affected only a small percentage of products, **we are requesting you contact us about returning your product for expedited servicing as soon as possible. This service is performed at no cost, and we expect the process to take between 7-10 business days, if not earlier.**

Maxim Product Number	Product Description
MXM-47822	Maxim MDX: SP 505 PDX - 300 BLK – ARID Pistol
MXM-47823	Maxim MDX: SP 505 PDX - 300 BLK – BLACK Pistol
MXM-47826	Maxim MDX 505 PDX Mil-Spec Upper - 300 BLK - ARID
MXM-47827	Maxim MDX 505 PDX Mil-Spec Upper - 300 BLK - BLACK
MXM-47828	Maxim MDX 505 PDX Upper Kit - 300 BLK - ARID
MXM-47829	Maxim MDX 505 PDX Upper Kit - 300 BLK - BLACK
MXM-47836	Maxim MDX 505 PDX Upper - 300 BLK - ARID
MXM-47837	Maxim MDX 505 PDX Upper - 300 BLK – BLACK

How to Start Your Return:

- Email us directly at safety@maximdefense.com
 - Be sure to include the following information in your email:
 - Your Full Name
 - Address
 - Best Telephone Number to Reach You
 - Maxim Product Number
 - PDX Firearm Serial Number (if applicable)
- Or you can call us at 239-216-2754.
 - Please have your PDX Serial Number (if applicable), and your Maxim Product Number ready for when you call.

Maxim Defense Industries is committed to 100% customer satisfaction, and we thank you for your loyalty.